

INFINITI U1205: GPS ROM

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$250-\$1000
Can I Still Drive?	:	Yes

What Does The Infiniti U1205 Code Mean?

An internal malfunction is detected in AV control unit (GPS malfunction). An intermittent error caused by strong radio interference may be detected unless any symptom (GPS reception error, etc.) occurs.

How Can You Fix The Infiniti U1205 Code?

Replace AV control unit.

Reference Sources

[Infiniti M35/M45 Y50 Service Repair Manual](#) - 2007, page AV-105