

JEEP B10B9: CABIN HEATER 2 CONTROL CIRCUIT HIGH

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$500
Can I Still Drive?	:	Yes (Short-term only)

What Does The Jeep B10B9 Code Mean?

With the ignition on, the Cabin Heater Relay 2 is commanded on. If the Totally Integrated Power Module detects a short to voltage on the (K232) Cabin Heater Relay 2 Control circuit, this code will set.

What Are The Potential Causes Of The Jeep B10B9 Code?

- (K232) cabin heater relay 2 control circuit shorted to voltage
- Cabin heater relay 2
- Totally integrated power module (TIPM)

Reference Sources

[Jeep B10B9](#), DTCDECODE.