

JEEP B10BE: CONDENSER FAN CONTROL CIRCUIT LOW

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$450-\$900
Can I Still Drive?	:	Yes (Short-term only)

What Does The Jeep B10BE Code Mean?

The Totally Integrated Power Module (TIPM) detects a shorted low condition in the (C123) Condenser Fan Control circuit.

What Are The Potential Causes Of The Jeep B10BE Code?

- (C123) condenser fan control output circuit shorted to ground
- Condenser fan motor
- TIPM

Reference Sources

[Jeep B10BE](#), DTCDECODE.