ST CF	RANKSHAFT PULSE SI	GNAL
	OVERVIEW	
:	Medium	
:	Intermediate	
:	\$75-\$200	
:	Yes	
	:	: Intermediate : \$75-\$200

What Does The Jeep B154F Code Mean?

The Amplifier (AMP) does not detect the engine crankshaft pulse signal from the PCM.

What Are The Potential Causes Of The Jeep B154F Code?

- Crankshaft pulse signal circuit shorted to voltage
- Crankshaft pulse signal circuit open
- Crankshaft pulse signal circuit shorted to ground
- PCM
- Amplifier

Reference Sources

Jeep B154F, DTCDECODE.

