

Jeep C121C: Torque Request Signal Denied

OVERVIEW

Severity

:

High

DIY Difficulty Level

:

Intermediate

Repair Cost

:

\$500-\$800

Can I Still Drive?

:

No

What Does The Jeep C121C Code Mean?

Powertrain Control Module (PCM) informed the Anti-lock Brake System (ABS) Module that it will not allow the engine torque reduction requests. Engine is above 360 rpm.

What Are The Potential Causes Of The Jeep C121C Code?

- Excessive Load On Engine
- Anti-Lock Brake System (ABS) Module
- Powertrain Control Module (PCM)

How Can You Fix The Jeep C121C Code?

- Repair damaged terminals/connectors/wiring harness
- Repair open/short together/short to ground/short to voltage circuits

Reference Sources

[Jeep Grand Cherokee WK](#)- 2005, pp. 5-252 - 5-257.