

What Does The Jeep P1480 Code Mean?

Engine started and the PCM detected an unexpected voltage on the PCV Solenoid circuit.

What Are The Potential Causes Of The Jeep P1480 Code?

- PCV solenoid control circuit is open or shorted to ground
- PCV solenoid power circuit is open to the fuse in the PDC
- PCV solenoid is damaged or has failed
- PCM has failed

Reference Sources

Jeep P1480, DTCDECODE.

