

JEEP P1498: NO CCD MESSAGES RECEIVED FROM THE TCM

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$400-\$1000
Can I Still Drive?	:	Yes (Short-term only)

What Does The Jeep P1498 Code Mean?

Key on or engine running; and the PCM detected a failure to communicate with the TCM over the CCD data Bus circuit

What Are The Potential Causes Of The Jeep P1498 Code?

- CCD data Bus circuit is open, shorted to ground or to power
- TCM or the PCM has failed

Reference Sources

[Jeep P1498](#), DTCDECODE.