

JEEP P1704: INPUT SPEED SENSOR 1 OVERSPEED

OVERVIEW

| | | |
|----------------------|---|------------------------------------|
| Severity | : | <div><div>High</div></div> |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost | : | \$100-\$350 |
| Can I Still Drive? | : | No |

What Does The Jeep P1704 Code Mean?

Continuously with the ignition on, engine running, transmission in gear, and Input Speed Sensor 1 (N2) greater than 0 RPM. If the RPM of the Input Speed Sensor 1 (N2) is greater than 7700 RPM.

What Are The Potential Causes Of The Jeep P1704 Code?

- Internal transmission
- Transmission control module (TCM)

Reference Sources

[Jeep Grand Cherokee WK](#)- 2005, pp. 21-584 - 21-586.