

## JEEP P1731: INCORRECT GEAR ENGAGED

### OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$100-\$850
Can I Still Drive?	:	No

### What Does The Jeep P1731 Code Mean?

The purpose of this diagnostic is to detect if a change in transmission gear position has occurred that was not requested.

### What Are The Potential Causes Of The Jeep P1731 Code?

- Low fluid level
- Transmission solenoid, speed sensor, or other electrical related dtcs present
- Intermittent sticking valve in valve body
- Transmission internal problem
- Transmission control module (TCM)

### Reference Sources

[Jeep Grand Cherokee WK](#)- 2005, pp. 21-590 - 21-591.