

JEEP P1794: A/T SPEED SENSOR GROUND CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$150-\$800
Can I Still Drive?	:	No

What Does The Jeep P1794 Code Mean?

Engine started; gear selector position indicating Neutral, and the PCM an error in the Output Speed Sensor signal during the test

What Are The Potential Causes Of The Jeep P1794 Code?

- Extremely low battery (system) voltage
- TCM "reset" function has just been performed

Reference Sources

[Jeep Grand Cherokee WK](#)- 2005, pp. 21-271 - 21-275.