KIA P1499: EGR STEPPER MOTOR 4 CIRCUIT MALFUNCTION			
		OVERVIEW	
Severity	:	Medium	
DIY Difficulty Level	:	Adv	anced
Repair Cost	:	\$450-\$600	
Can I Still Drive?	:	Yes (Short-term only)	

What Does The Kia P1499 Code Mean?

Key on or engine running and PCM detected an unexpected voltage condition on the EGR Stepper Motor 4 circuit during the CCM test.

What Are The Potential Causes Of The Kia P1499 Code?

- EGR stepper motor 4 control circuit open or shorted to ground
- EGR stepper motor 4 power circuit is open to the Main Relay
- EGR stepper motor 4 is damaged or has failed
- PCM has failed (EGR stepper motor 4 "driver" circuit is open)

Reference Sources

Kia P1499, DTCDECODE.

