

KIA P1693: TRANSPONDER NO RESPONSE ERROR/INVALID RESPONSE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$60-\$90
Can I Still Drive?	:	Yes (Short-term only)

What Does The Kia P1693 Code Mean?

Enable Conditions: IG ON, Threshold value Corrupted data from Transponder More than one TP in the magnetic field, No TP(Key without TP) in the magnetic field

What Are The Potential Causes Of The Kia P1693 Code?

Invalid transponder.

Reference Sources

[Immobilizer Repair Information for P1693](#) - Chonan Technical Service Training Center, page 17.