

## LEXUS B1247: TIRE PRESSURE MONITOR RECEIVER COMMUNICATION STOP

### OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Lexus B1247 Code Mean?

Tire pressure warning ECU receiver communication stops.

### What Are The Potential Causes Of The Lexus B1247 Code?

- Tire pressure warning ECU
- Wire harness

### Reference Sources

[Lexus B1247](#), DTCDECODE.