

Lexus P1749: A/T Shift Solenoid 'C' Control Circuit High Input

OVERVIEW

Severity

:

Medium

DIY Difficulty Level

:

Intermediate

Repair Cost

:

\$200-\$500

Can I Still Drive?

:

Yes (Short-term only)

What Are The Potential Causes Of The Lexus P1749 Code?

- A/T SSC control circuit is open between the solenoid and PCM
- A/T SSC control circuit is shorted to system power (B+)
- A/T SSC is damaged or has failed (it may be shorted)
- PCM has failed

Reference Sources

[Lexus P1749](#), DTCDECODE.