

MAZDA C1214: RF INLET SOLENOID VALVE SYSTEM

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	No

What Does The Mazda C1214 Code Mean?

Solenoid valve operation does not correspond to solenoid ON/OFF commands from the ABS or DSC HU/CM.

What Are The Potential Causes Of The Mazda C1214 Code?

- Solenoid valve malfunction
- Open or short circuit in the ABS or DSC HU/CM internal solenoid valves
- Poor connection at connectors (female terminal)

Reference Sources

[Mazda C1214](#), DTCDECODE.