

Mazda C1280: Yaw Rate Sensor In SAS Control Module Is Signal Error

OVERVIEW

Severity

:

High

DIY Difficulty Level

:

Advanced

Repair Cost

:

\$550-\$750

Can I Still Drive?

:

No

What Does The Mazda C1280 Code Mean?

WARNING: Detection conditions are for understanding the DTC outline before performing an inspection. Performing an inspection with only detection conditions may cause injury due to an operating error, or damage the system. When performing an inspection, always follow the inspection procedure. Malfunction in the SAS control module.

What Are The Potential Causes Of The Mazda C1280 Code?

SAS control module malfunction

Reference Sources

[Mazda C1280](#), DTCDECODE.