

Mercedes-Benz P1177: Oil Sensor Signal re Oil Temperature Implausible

OVERVIEW

Severity

:

High

DIY Difficulty Level

:

Intermediate

Repair Cost

:

\$100-\$1100

Can I Still Drive?

:

No

What Are The Potential Causes Of The Mercedes-Benz P1177 Code?

- Wrong actual value or oil sensor re oil level, temperature and quality
- Deficient power supply of oil sensor

Reference Sources

[Mercedes-Benz P1177](#), DTCDECODE.