

MERCEDES-BENZ P1177: OIL SENSOR SIGNAL RE OIL TEMPERATURE IMPLAUSIBLE

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$1100
Can I Still Drive?	:	No

What Are The Potential Causes Of The Mercedes-Benz P1177 Code?

- Wrong actual value or oil sensor re oil level, temperature and quality
- Deficient power supply of oil sensor

Reference Sources

[Mercedes-Benz P1177](#), DTCDECODE.