

What Are The Potential Causes Of The Mercedes-Benz P1178 Code?

- Wrong actual value or oil sensor re oil level, temperature and quality.
- Deficient power supply of oil sensor.

Reference Sources

Mercedes-Benz P1178, DTCDECODE.

