

MERCEDES-BENZ P1181: ENGINE/CLIMATE CONTROL ELECTRIC COOLING FAN MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$500-\$300
Can I Still Drive?	:	No

What Are The Potential Causes Of The Mercedes-Benz P1181 Code?

Wiring/connectors

Reference Sources

[Mercedes-Benz P1181](#), DTCDECODE.