

MERCEDES-BENZ P1185: WATER IN ENGINE OIL

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$2500
Can I Still Drive?	:	No

What Are The Potential Causes Of The Mercedes-Benz P1185 Code?

- Check component oil sensor.
- Check power supply to oil sensor.

Reference Sources

[Mercedes-Benz P1185](#), DTCDECODE.