

MERCEDES-BENZ P1366: EXHAUST FLAP SWITCHOVER VALVE

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$150-\$700
Can I Still Drive?	:	No

What Are The Potential Causes Of The Mercedes-Benz P1366 Code?

- Test actuation of exhaust flap switchover valve.
- Test current consumption of exhaust flap switchover valve.

Reference Sources

[Mercedes-Benz P1366](#), DTCDECODE.