

MERCEDES-BENZ P1580: EA/CC/ISC ACTUATOR (THROTTLE VALVE ACTUATOR)

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$500-\$1500
Can I Still Drive?	:	Yes (Short-term only)

What Are The Potential Causes Of The Mercedes-Benz P1580 Code?

Wiring/connectors

Reference Sources

[Mercedes-Benz P1580](#), DTCDECODE.