MERCEDES-BENZ P1580: EA/CC/ISC ACTUATOR (THROTTLE VALVE ACTUATOR) OVERVIEW

Severity : High

DIY Difficulty Level : Advanced

Repair Cost : \$500-\$1500

Can I Still Drive? : Yes (Short-term only)

What Are The Potential Causes Of The Mercedes-Benz P1580 Code?

Wiring/connectors

Reference Sources

Mercedes-Benz P1580, DTCDECODE.

