

## MERCEDES-BENZ P1642: ENGINE CONTROL MODULE INCORRECTLY CODED

### OVERVIEW

|                      |   |             |
|----------------------|---|-------------|
| Severity             | : | High        |
| DIY Difficulty Level | : | Advanced    |
| Repair Cost          | : | \$100-\$500 |
| Can I Still Drive?   | : | No          |

### How Can You Fix The Mercedes-Benz P1642 Code?

Check version coding and correct.

### Reference Sources

[Mercedes-Benz P1642](#), DTCDECODE.