

MERCEDES-BENZ P1999: IDLE SPEED ABOVE OR BELOW LIMITS

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$100-\$1500
Can I Still Drive?	:	No

What Does The Mercedes-Benz P1999 Code Mean?

Engine idle and running condition affected. Idle speed with warm engine is above the permissible range limit.

What Are The Potential Causes Of The Mercedes-Benz P1999 Code?

- Intake system leaks
- Throttle valve actuator

Reference Sources

[Mercedes-Benz P1999](#), DTCDECODE.