ACTUATOR CIRCUIT MALFUNCTION			
		OVERVIEW	
Severity	:		High
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$150-\$710	

What Does The Mitsubishi P1103 Code Mean?

Engine started, ECT sensor more than 176 F, TP sensor signal less than 4.2v, and the PCM detected the volumetric efficiency remained at over 200% for 1.5 seconds during the CCM Rationality test.

What Are The Potential Causes Of The Mitsubishi P1103 Code?

- Turbocharger Wastegate actuator is damaged or has failed
- Boost Pressure Control system has failed
- PCM has failed

Reference Sources

Mitsubishi P1103, DTCDECODE.

