

## NISSAN B2630: SUNLOAD SENSOR

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$350
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Nissan B2630 Code Mean?

Detected calorie at sunload sensor 2832 W/m<sup>2</sup> (2436 kcal/m<sup>2</sup>·h) or more.

### What Are The Potential Causes Of The Nissan B2630 Code?

- Sunload sensor
- A/C auto amp
- Harness and connector (short in the sunload sensor circuit)

### Reference Sources

[HEATER & AIR CONDITIONING CONTROL SYSTEM SERVICE MANUAL for B2630](#) - 2009 Murano, pages 53-55.