NISSAN C1176: STOP LAMP SWITCH 2		
OVERVIEW		
:	Medium	
:	Intermediate	
: \$!	50-\$150	
: Y	es	
	OVE	

What Are The Potential Causes Of The Nissan C1176 Code?

- Harness and connectors
- Check circuit for open, short or damaged connections
- ASCD brake switch or circuit

Reference Sources

Nissan C1176, DTCDECODE.

