

SAAB P1086: TUMBLE GENERATED VALVE POSITION SENSOR CIRCUIT LOW

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	No

What Are The Symptoms Of The Saab P1086 Code?

Engine stalls. Erroneous idling. Poor driving performance.

How Can You Fix The Saab P1086 Code?

- Using a scan tool, check current data
- Check input signal for Control module
- Check harness between Control module and tumble generator valve position sensor connector
- Check poor contact

Reference Sources

[Saab P1086](#), DTCDECODE.