

SAAB P1087: TUMBLE GENERATED VALVE POSITION SENSOR CIRCUIT HIGH

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	No

What Are The Symptoms Of The Saab P1087 Code?

Engine stalls. Erroneous idling. Poor driving performance.

How Can You Fix The Saab P1087 Code?

- Using a scan tool, check current data
- Check harness between tumble generator valve position sensor and Control module connector
- Check harness between throttle position sensor and Control module connector

Reference Sources

[Saab P1087](#), DTCDECODE.