

## SAAB P1090: TUMBLE GENERATED VALVE SYSTEM 1 (VALVE OPEN)

### OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$450-\$800
Can I Still Drive?	:	No

### What Are The Symptoms Of The Saab P1090 Code?

Engine stalls. Erroneous idling. Poor driving performance.

### How Can You Fix The Saab P1090 Code?

- Check any other DTC on display
- Check tumble generator valve (RH)

### Reference Sources

[Saab P1090](#), DTCDECODE.