

SAAB P1092: TUMBLE GENERATED VALVE SYSTEM 2 (VALVE OPEN)

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$450-\$800
Can I Still Drive?	:	No

What Are The Symptoms Of The Saab P1092 Code?

Engine stalls. Erroneous idling. Poor driving performance.

How Can You Fix The Saab P1092 Code?

- Check any other DTC on display
- Check tumble generator valve (RH)

Reference Sources

[Saab P1092](#), DTCDECODE.