

## SUBARU B1104: ACC POWER FAILURE

### OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

### What Does The Subaru B1104 Code Mean?

ACC power supply circuit voltage is too high or too low. Ignition switch turns to ACC with the weak battery condition.

### What Are The Potential Causes Of The Subaru B1104 Code?

- Loose wiring harness connection
- Defective fuse
- Bad wiring harness
- Open or short circuit between body integrated unit and fuse
- Poor contact in Body Integrated Unit connector

### Reference Sources

[Testing and Inspection for B1104](#) - 2009 Subaru Impreza Repair Manual, pages 3378-3379.