

What Does The Subaru B1106 Code Mean?

Shift lock circuit is open or shorted. Shift lock does not be released or remain locked.

What Are The Potential Causes Of The Subaru B1106 Code?

- Loose wiring harness connection
- Defective shift lock solenoid
- Bad wiring harness

Reference Sources

Testing and Inspection for B1106 - 2009 Subaru Impreza Repair Manual, pages 3382-3383.

