

## SUBARU P1092: TUMBLE GENERATED VALVE SYSTEM 2 (VALVE OPEN)

### OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$450-\$800
Can I Still Drive?	:	No

### What Does The Subaru P1092 Code Mean?

Engine stalls. Erroneous idling. Poor driving performance.

### What Are The Potential Causes Of The Subaru P1092 Code?

- Check any other DTC on display
- Check tumble generator valve (RH)

### Reference Sources

[Testing and Inspection for P1092](#) - 2004 FORESTER SERVICE MANUAL, page 200.