

SUBARU P1131: FRONT OXYGEN SENSOR CIRCUIT MALFUNCTION (SHORT CIRCUIT)

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes

What Does The Subaru P1131 Code Mean?

Engine started, engine runtime over 3 minutes, and the PCM detected an unexpected "high" voltage condition on the front A/F Sensor (A/FS) signal circuit for 10 seconds during the CCM test.

How Can You Fix The Subaru P1131 Code?

- Check harness between ECM and sensor connector
- Check output signal for ECM

Reference Sources

[Subaru Impreza Repair Manual for P1131](#) - Pages 596-597.