

SUBARU P1140: BANK 2 AND SENSOR 1 OXYGEN SENSOR (FRONT LEFT) HEATER CIRCUIT RANGE/ PERFORMANCE PROBLEM

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes

What Does The Subaru P1140 Code Mean?

Engine started, engine runtime over 3 minutes, and the PCM detected an unexpected "high" current condition on the front A/F Sensor (A/FS) signal circuit for 10 seconds during the CCM test.

How Can You Fix The Subaru P1140 Code?

- Check harness between ECM and sensor connector
- Check front sensor
- Check poor contact

Reference Sources

[Subaru P1140](#), DTCDECODE.