

## SUBARU P1141: MASS AIR FLOW SENSOR CIRCUIT RANGE/PERFORMANCE PROBLEM (HIGH OUTPUT)

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$500
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Subaru P1141 Code Mean?

DTC P0102 and P0103 not set, Engine started, engine running at idle or cruise speed, and the PCM detected an unexpected "high" voltage condition on the MAF sensor circuit during the CCM test.

### What Are The Potential Causes Of The Subaru P1141 Code?

Check any other DTC on display

### Reference Sources

[2001 FORESTER SERVICE MANUAL FOR P1141](#) - Pages 297-298.