

SUBARU P1142: THROTTLE POSITION SENSOR CIRCUIT RANGE/PERFORMANCE PROBLEM (LOW INPUT)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$600
Can I Still Drive?	:	Yes (Short-term only)

What Does The Subaru P1142 Code Mean?

DTC [P0122](#) and [P0123](#) not set, Engine started, engine running at idle or cruise speed, and the PCM detected an unexpected "low" voltage condition on the TP sensor circuit during the CCM test.

What Are The Potential Causes Of The Subaru P1142 Code?

Check any other DTC on display

Reference Sources

[Subaru Impreza Repair Manual for P1142](#) - Page 605.