

SUBARU P1151: REAR OXYGEN SENSOR HEATER CIRCUIT HIGH INPUT

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes

What Are The Symptoms Of The Subaru P1151 Code?

Poor Drivability

How Can You Fix The Subaru P1151 Code?

- Check input signal for ECM
- Check any other DTC on display

Reference Sources

[Subaru Impreza Repair Manual for P1151](#) - Pages 606-607.