




SUBARU P1154: BANK 1 AND SENSOR 1 OXYGEN SENSOR (FRONT LEFT) CIRCUIT RANGE/PERFORMANCE PROBLEM LOW INPUT

OVERVIEW

Severity	:	 High
DIY Difficulty Level	:	 Intermediate 
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes

What Are The Symptoms Of The Subaru P1154 Code?

Poor drivability

How Can You Fix The Subaru P1154 Code?

- Check any other DTC on display
- Using a scan tool, check current data
- Check rear sensor signal
- Check exhaust system

Reference Sources

[Diagnostic Trouble Code \(DTC\) Detecting Criteria for P1154](#) - Page 181