




SUBARU P1155: BANK 2 AND SENSOR 1 OXYGEN SENSOR (FRONT LEFT) CIRCUIT RANGE/PERFORMANCE PROBLEM HIGH INPUT

OVERVIEW

Severity	:	 High
DIY Difficulty Level	:	 Intermediate 
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Are The Symptoms Of The Subaru P1155 Code?

Poor drivability.

What Are The Potential Causes Of The Subaru P1155 Code?

- Check any other DTC on display
- Using a scan tool, check current data
- Check rear sensor signal
- Check exhaust system

Reference Sources

[Diagnostic Trouble Code \(DTC\) Detecting Criteria for P1155](#) - Page 181