

SUBARU P1312: EXHAUST GAS TEMPERATURE SENSOR MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$300
Can I Still Drive?	:	Yes

What Are The Symptoms Of The Subaru P1312 Code?

Poor drivability

How Can You Fix The Subaru P1312 Code?

- Check any other DTC on display
- Using a scan tool, check current data

Reference Sources

[2001 FORESTER SERVICE MANUAL FOR P1312](#) - Pages 311-312.