

SUBARU P1410: SECONDARY AIR INJECTION SYSTEM SWITCHING VALVE STUCK OPEN

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$400
Can I Still Drive?	:	Yes

What Are The Symptoms Of The Subaru P1410 Code?

Poor drivability

How Can You Fix The Subaru P1410 Code?

- Using the a scan tool, check current data
- Check harness between mass air flow and intake air temperature sensor and ECM

Reference Sources

[2008 Impreza WRX Repair Manual for P1410](#) - Pages 266-268.