

SUBARU P1418: SECONDARY AIR INJECTION SYSTEM CONTROL "A" CIRCUIT SHORTED

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$400
Can I Still Drive?	:	Yes (Short-term only)

What Are The Symptoms Of The Subaru P1418 Code?

Poor drivability.

How Can You Fix The Subaru P1418 Code?

- Using a scan tool, check current data
- Check harness between mass air flow and intake air temperature sensor and ECM

Reference Sources

[2008 Impreza WRX Repair Manual for P1418](#) - Pages 269-271.