

SUBARU P1423: EVAPORATIVE EMISSION CONTROL SYSTEM VENT CONTROL HIGH INPUT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$150-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Subaru P1423 Code Mean?

Key on or engine running; and the PCM detected an unexpected "high" voltage condition on the EVAP Vent Control solenoid circuit during the CCM test.

What Are The Potential Causes Of The Subaru P1423 Code?

- Check output signal of ECM
- Check poor contact
- Check harness between vent control solenoid valve and ECM connector
- Check vent control solenoid valve

Reference Sources

[Subaru Impreza Repair Manual for P1423](#) - Pages 632-634.