

## SUBARU P1447: FUEL TANK SENSOR CONTROL VALVE CIRCUIT HIGH

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$300
Can I Still Drive?	:	Yes

### What Does The Subaru P1447 Code Mean?

Engine started, and the PCM detected an unexpected high voltage condition on the Atmospheric Pressure valve circuit during the test.

### How Can You Fix The Subaru P1447 Code?

- Check output signal from ECM
- Check poor contact
- Check harness between fuel tank sensor control valve and ECM connector
- Check fuel tank sensor control valve

### Reference Sources

[Subaru P1447](#), DTCDECODE.