

SUBARU P1494: EGR SOLENOID VALVE SIGNAL #2 CIRCUIT MALFUNCTION (LOW INPUT)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes

What Are The Symptoms Of The Subaru P1494 Code?

- Improper idling
- Poor driving performance
- Engine breathing.

What Are The Potential Causes Of The Subaru P1494 Code?

- Wiring harness between EGR valve and power supply needs repair
- Wiring harness between ECM and EGR valve connector needs repair
- Poor contact in the ECM and EGR valve connector
- Defective EGR valve

Reference Sources

[DIAGNOSTIC PROCEDURE WITH DIAGNOSTIC TROUBLE CODE FOR P1494](#) - Page 158.