

## SUBARU P1495: EGR SOLENOID VALVE SIGNAL #2 CIRCUIT MALFUNCTION (HIGH INPUT)

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Are The Symptoms Of The Subaru P1495 Code?

Improper idling. Poor driving performance. Engine breathing.

### What Are The Potential Causes Of The Subaru P1495 Code?

- Wiring harness between ECM and EGR valve connector needs repair.
- Wiring harness between ECM and chassis ground needs repair.
- Poor contact in the ECM and EGR valve connector.

### Reference Sources

[DIAGNOSTIC PROCEDURE WITH DIAGNOSTIC TROUBLE CODE FOR P1495](#) - Page 158.